TOLERANCES

CF ALLOY BARS

Cold Drawn or Turned & Polished

	COIL DIAW	ii or furneu a Pon	Sileu				
Undersize Variations in Inches							
Specified Size in Inches	Max. Carbon Range .28% or less	Max. Carbon Range over .28 to .55% incl.	AnnId. or Stress Relieved after C.F. Max. carb. to .55%	Max. Carbon range over 0.55% with or without stress relieving or annealing after cold finishing. Also all carbons Heat Tr. or Norm. & Temp. before cold Finishing			
To 1 incl. (in coils)	.002	.003	.004	.005			
To $1\frac{1}{2}$ incl.	.003	.004	.005	.006			
Over 11/2 to 21/2	.004	.005	.006	.007			
Over 21/2 to 4	.005	.006	.007	.008			
Over 4 to 6	.006	.007	.008	.009			
Over 6 to 8	.007	.008	.009	.010			
Over 8 to 9	.008	.009	.010	.011			
Over 9	.009	.010	.011	.012			
	COLD DI	RAWN HEXAGO	ONS				
To ³ / ₄ , incl.	.003	.004	.005	.007			
Over $\frac{3}{4}$ to $1\frac{1}{2}$.004	.005	.006	.008			
Over $1\frac{1}{2}$ to $2\frac{1}{2}$.005	.006	.007	.009			
Over 21/2 to 31/8	.006	.007	.008	.010			
	COLD	RAWN SQUAR	ES				
To ³ / ₄ , incl.	.003	.005	.006	.008			
Over $\frac{3}{4}$ to $1\frac{1}{2}$.004	.006	.007	.009			
Over $1\frac{1}{2}$ to $2\frac{1}{2}$.005	.007	.008	.010			
Over 2 ¹ / ₂ to 4	.007	.009	.010	.012			
Over 4 to 5	.011	ar e dat e date					
Tole	• •	DRAWN FLAT	-)			
Width in Inches							
To ³ / ₄ , incl.	.004	.005	.007	.009			
Over $\frac{3}{4}$ to $1\frac{1}{2}$.005	.006	.009	.011			
		007	044	010			

To $\frac{34}{4}$, incl.	.004	.005	.007	.009
Over $\frac{3}{4}$ to $1\frac{1}{2}$.005	.006	.009	.011
Over $1\frac{1}{2}$ to 3	.006	.007	.011	.013
Over 3 to 4	.007	.009	.012	.017
Over 4 to 6	.009	.011	.013	.021
Over 6	.014			

COLD DRAWN, GROUND AND POLISHED ROUNDS TURNED, GROUND AND POLISHED ROUNDS

	Cold Drawn, Ground & Polished All Carbons with		Turned, Ground & Polished		
Diameter in Inches	or without thermal treatment before Cold Drawing		Not Heat Treated All Carb.	Heat* Treated All Carb.	
To 1½ incl.	.001	.0005	.0015	.0015	
Over 11/2 to 21/2, excl.	.0015	.0005	.0020	.0020	
21/2 to 3, incl.	.002	.0005	.0025	.0025	
Over 3 to 4, incl.	.003	.0005	.0035	.0035	
Over 4 to 6, incl.		.0005	.0045	.0045	
Over 6		.0005	.0055	.0055	

*All tolerances are on the minus side, +.000. Applies to quenched and tempered (heat treated), normalized and tempered, or any similar double treatment prior to turning.